

# FORD BRONCO

## OWNER CHECKLIST for DELIVERY (OCD)

\*\*Revision 7\*\* Dec 18, 2021

### Ford Pass Rewards Points:

- ☐ 200,000 Bronco Roof Bonus - (original orders for Mod Painted Hard or Dual)
- ☐ 11,000 User Appreciation Points
- ☐ 20,000 Bronco Reservationist Thank You Bonus (prior to March 25, 2021)
- ☐ 42,000 New Vehicle Purchase
- ☐ 1,100 converting order before March 19th

Customer Satisfaction Funds: \$1,000. Have your dealer go to the FDAD CLAIM PAGE on the Dealers Bronco Dashboard, if they don't know about it.

- ☐ Bronco Swag Bag (first 100 Bronco orders per Dealer)

Extended Warranty: Floodfordesp.com.

Sample deals:

PremiumCare 8yr/100K \$0 warranty for \$2060. It's a no brainer!

8 yrs 100,00 miles. \$1600 to Flood for 8/100,000. \$200 deductible.

[https://www.floodfordesp.com/esp\\_pl...2=0&Surcharge5=0&Surcharge3=0&Submit=Continue](https://www.floodfordesp.com/esp_pl...2=0&Surcharge5=0&Surcharge3=0&Submit=Continue)

Can use FordPass Points (see FAQs.)

Ensure you receive your Price Protection Certificate for MY21 orders pushed to MY22 orders prior to March 19, 2021.

<https://www.bronco6g.com/forum/threads/price-protection.30423/>

	BRONCO 2-DOOR	BRONCO 4-DOOR
Base	\$800	\$250
Big Bend	\$400	\$250
Black Diamond	\$975	\$825
Outer Banks	\$400	\$250
Wildtrak	\$800	\$695
Badlands	\$975	\$825

## OWNER CHECKLIST for DELIVERY (OCD)

---

### Inspection Checklist (based on Bronco6g OP repetitive feedback):

#### Mechanical

- ☐ Pulley rub/ proximity next to radiator hose
- ☐ Coolant hose clamp tight
- ☐ Battery terminals tight (negative loose)
- ☐ Turbo Charge Air Cooler Hose securely attached to the Charge Air Cooler Pipe (these are the big black tubes in the engine compt)
- ☐ Roll all windows up at once
- ☐ Check window auto-drop for excessive snag/wobble. Reset windows by holding switches down for 10 secs.
- ☐ Tailgate hinge area and fuel door has paint issues
- ☐ Fluids all full (oil, washer, brake)
- ☐ Confirm SEVEN Quarts of oil filled, not six. It's a 7 qt pan with a 6 qt dipstick. Ref:

<https://forum/threads/bronco-team-engineering-confirms-7-0-quarts-for-2-7l-engine-oil-change-is-correct.29047/>

- ☐ Strut on the back window unglued from the hardtop (why not drilled in??)
- ☐ Check all three bolts in the fuse box for looseness
- ☐ Alternator belt installed backwards (smooth side against pulley)
- ☐ Transfer case wire harness rubbing against drive shaft (missing plastic clamp)

#### Paint/Exterior

- ☐ MIC Hardtop rough/sharp edges, gaps, leaks, roof rattles, popping from guide pins, latches...especially seal in middle
- ☐ MIC panels all match in color, not two-tone
- ☐ MIC Panels contacting, rubbing body panels, especially around rear corner panels/tailgate. Source os squeaks.
- ☐ Soft top frame rubbing, seal alignment, fitment
- ☐ Paint bubbles/paint defects
- ☐ Paint overspray on windshield and body panels. (Rough to touch vs. baby/glass smooth)
- ☐ Missing paint in door jambs/door brackets (may need to remove doors to see hinges in jambs), tailgate, fuel door
- ☐ Body panel alignment
- ☐ Hood dents on pax side caused by excessive panel bond on cross bars

## OWNER CHECKLIST for DELIVERY (OCD)

---

- ☐ No license plate mounting (if mounting alternate location)
- ☐ Check underneath for corrosion
- ☐ Check for transport damage
- ☐ Check for rail dust (small specs of rust that will corrode). Must be clay barred off and repainted, or try iron/rust remover

### Interior

- ☐ Test all roof latches (some missing)
- ☐ Check seat stitching and ensure seats match
- ☐ Check seat belt webbing for defects
- ☐ Sound deadening installed (hardliner)
- ☐ Interior and trunk lights/bulbs work
- ☐ Owners Manual and Tool kit in glovebox
- ☐ Any TSBs/ Service Alerts? A-pillar leak TSB: 21-2403
- ☐ Whistling mirrors
- ☐ Ensure floor mats are as ordered (Raptor/Warthog/Ranger logo mats installed in Bronco)

### Miscellaneous

- ☐ Full tank of gas (we paid for it!)
- ☐ Door bags
- ☐ Mismatched roll bars...holes drilled on one, but not the other
- ☐ Ensure all cameras work
- ☐ Check windshield washer bottle neck for zip-tie support (should not be there)
- ☐ Test Windshield Wiper reservoir is full and sprays fluid on windshield

Dealer Signature: \_\_\_\_\_ Date: \_\_\_\_\_

Owner Signature: \_\_\_\_\_ Date: \_\_\_\_\_